



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/TPS/QAR12.0003/11	Page 1 of 1
QAR Free Ref. No.:	713295097_QAR	Status: Issued
Details of change:	Re-Certification Assessment	Date of issue: 2023-03-14
Site(s) audited:	KEM Küppers Elektromechanik GmbH Liebigstrasse 5 85757 Karlsfeld Germany	Valid until: 2026-03-07 Audit date: 2023-03-07
	KEM Küppers Elektromechanik GmbH Wetzellerstraße 22 93444 Kötzing Germany	
Issuing ExCB:	TPS - TÜV SÜD Product Service GmbH	
Manufacturer:	KEM Küppers Elektromechanik GmbH Liebigstraße 5 85757 Karlsfeld Germany	
Location of Manufacturer:	Germany	
Product information:	Mass meters, amplifiers, power supply units, sensors in types of protection: "e", "i", "d" and "t"	
Protection concept:	protection by intrinsic safety "i" , flameproof enclosure "d" increased safety "e" dust ignition protection by enclosure "t"	
Related QARs:		
DE/TPS/QAR12.0003/00	DE/TPS/QAR12.0003/01	DE/TPS/QAR12.0003/02
DE/TPS/QAR12.0003/03	DE/TPS/QAR12.0003/04	DE/TPS/QAR12.0003/05
DE/TPS/QAR12.0003/06	DE/TPS/QAR12.0003/07	DE/TPS/QAR12.0003/08
DE/TPS/QAR12.0003/09	DE/TPS/QAR12.0003/10	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX BVS 09.0053 issue: 2	IECEX BVS 12.0098X issue: 0	IECEX BVS 12.0098X issue: 1
IECEX BVS 12.0098X issue: 2	IECEX BVS 12.0098X issue: 3	IECEX BVS 12.0098X issue: 4
IECEX BVS 13.0066 issue: 0	IECEX BVS 13.0129 issue: 0	IECEX BVS 13.0129 issue: 1
IECEX BVS 15.0002 issue: 0	IECEX BVS 17.0037 issue: 0	IECEX BVS 17.0037 issue: 1
IECEX BVS 17.0056 issue: 0	IECEX SIR 10.0162U issue: 3	IECEX SIR 10.0162U issue: 4
IECEX SIR 15.0066X issue: 3	IECEX SIR 16.0089U issue: 0	IECEX SIR 16.0089U issue: 1
IECEX SIR 16.0089U issue: 2	IECEX SIR 18.0072X issue: 0	IECEX SIR 18.0077X issue: 0
IECEX SIR 19.0005X issue: 0	IECEX SIR 19.0006X issue: 0	IECEX SIR 20.0014X issue: 0
IECEX SIR 20.0015X issue: 0	IECEX ZLM 15.0001X issue: 0	
Comments:	There is a previous QAR by TPS (DE/TPS/QAR12.0003/10) which is updated by this QAR. The Re-Assessment was conducted parallel to the ATEX Re-Audit.	